JMM WETLAND CONSULTING SERVICES, LLC

23 Horseshoe Ridge Road Newtown, CT 06482

> Phone: 203-364-0345 Mobile: 203-994-3428 james@jmmwetland.com jmmwetland.com

April 5, 2023

Town of South Windsor Inland Wetlands Agency/Conservation Commission 1540 Sullivan Avenue South Windsor, CT 06074

RE: WETLANDS/WATERCOURSES DELINEATIONS
75 Connecticut Avenue, South Windsor, Connecticut

JMM Job # 21-2770-SWN-2

Dear Commissioners:

This letter report is a supplement to the On-Site Soil Investigation Report completed back on February 22, 2023. As you recall, JMM Wetland Consulting Services, LLC (JMM) completed a soil-based wetland delineation back on March 29th, 2021. At that time JMM demarcated regulated wetlands along the western and northern portions of the site. As can be seen from Figure 1, attached a previous delineation had somewhat less regulated areas than the more recent JMM regulated boundary.

The overall site is highly disturbed and was used several decades in the past for sand and gravel mining. JMM carefully reviewed the site's soils, focusing on the area where the more substantive difference between the two delineations was observed. Although these soils were predominately disturbed, active indicators such as oxidized rhizospheres and redoximorphic features (i.e., mottles) where present in sufficient amounts within the 20-inch diagnostic soil depth. Therefore, in JMM's opinion these soils are poorly drained, and thus, regulated as wetlands.

It is worth noting that an excavated ditch type feature left over from the former gravel mining was observed/reviewed within the eastern portion of the site for its regulatory status. After a careful review it was determined that feature is not a regulated intermittent watercourse.

Town of South Windsor IWWC75 Connecticut Avenue, South Windsor, CT
April 5, 2023 **Page 2**



Although technically this feature has a channel and bank, other characteristics necessary for an intermittent watercourse determination were not present. These include flow or ponding of water, and a hydrophytic vegetation community. Moreover, no poorly or very poorly drained soils were observed within this landscape feature.

Please call us if you have any questions on the above or need further assistance.

Respectfully submitted,

Jans M. Mil


JMM WETLAND CONSULTING SERVICES, LLC

James M. McManus, MS, CPSS

Certified Professional Soil Scientist (No. 15226)

Attachments: Figure 1

FIGURE 1: 75 Connecticut Avenue, South Windsor, CT Map Showing the Difference Between the Previous Delineation (in blue) and the JMM Wetland Delineation (in red).



48TO Engineering/AutoCADVASS Sie Planding Layouk C2 C-S91 Potted 3/31/2021 1241 PM Lust Saved 3/19/2021 1147 AM Lust Saved By glen